Release Date: December 24, 2014

VRMF Level Data Results:

VRMF level From:	87.21.39.0
VRMF Level To:	87.21.48.0
Report for:	All DS8870

Code Bundle Contents

This table includes code component reference information.

DS8870 Code Bundle Level	SEA or LMC Version:	DS CLI Client	Easy Tier Client		Heat Map Transfer Utility	Storage Manager
87.21.48.0	7.7.21.94	7.7.21.94	7.7.21.94	7.7.21.94	7.7.21.94	5.7.21.1050

Overview of new features and functions supported by this release on DS8870, 242x model 961

At a glance:

- Global Copy Collision enhancement enabled by default
- RAID10 rebuild duration reduction
- Apache Tomcat, AppScan, and other security fixes
- Battery end of life bug calculation DC UPS FW 03-47
- Easy Tier data collection improvement
- Reduce Secure Data Overwrite pre-check duration

This new microcode release only supports the DS8870.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact. Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

1 High Impact - Acute: An irrecoverable error with potential loss of data.

- Serious: An irrecoverable error with potential loss of access to data.

2 Moderate - A function not operational and/or performance might be degraded.

Service - A recoverable error (no impact) and service improvements.
 Improvements - Improvement changes for better Usability and Serviceability.

HIPER: High Impact problem that is Pervasive: 3 or more occurrences

Acute: An irrecoverable error with potential loss of data.

HIPER - Killstrip error logs are not processed by DA

1. Problem Description: Killstrip processing is delayed until the host executes a read to that location.

2. Potential Impact of Problem: loss of data

Problem Severity: HIPER
 Pervasive Problem: Yes

ID#: 299666

Inconsistencies on PPRC 'A' copy

1. Problem Description: When PPRC primary volume is cascaded, an indicator is lost that the volume is a primary. This allows flashcopy establish, without ensuring the flashcopy is being mirrored.

2. Potential Impact of Problem: Corrupted primary copy

3. Problem Severity: High Impact

4. Pervasive Problem: No

ID#: 300273

Serious: An irrecoverable error with potential loss of access to data.

PCIe last path recovery enhancement

1. **Problem Description:** During error recovery for a PCIe error to a host bay, access can be lost if we have latent PCIe errors on the alternate host bay. This change implements additional recovery strategies when a secondary error occurs on the last path.

2. Potential Impact of Problem: loss of access

3. Problem Severity: High Impact

4. Pervasive Problem: No

ID#: 298574

Moderate: A system path is not operational and performance may be degraded.

Excessive Easy Tier swap plan generation time

1. Problem Description: Multiple time-outs and MLEs caused by Easy Tier taking too long to generate swap plans, and missing heartbeats.

2. Potential Impact of Problem: degraded performance

Problem Severity: Moderate
 Pervasive Problem: Yes

ID#: 298152

IWNR2704E on Global Mirror session pause

1. **Problem Description:** When > 1 control paths are owned by the Master Alternate Controller (MAC), code does not properly iterate through all the external subordinates owned by the MAC.

2. Potential Impact of Problem: Global Mirror pause failure

3. Problem Severity: Moderate

4. Pervasive Problem: No

Service: A recoverable error, Service improvements.

PCR 7575 - DSGUI AppScan errors/security vulnerabilities

1. Problem Description: Corrects multiple vulnerabilities

2. Potential Impact of Problem: none

3. Problem Severity: Service4. Pervasive Problem: No

ID#: 294209

STAT workload skew report incorrect

1. **Problem Description:** We have two problems here:

- a) Extents are not sorted by bandwidth when generating the heat files;
- b) When generating the CSV files, code uses the extents sorted by the total I/O, instead of heat I/O;

These two problems cause an incorrect skew curve for bandwidth based on the CSV files

- 2. Potential Impact of Problem: Incorrect workload reporting
- Problem Severity: Service
 Pervasive Problem: No

ID#: 298335

False loss-of-access indication on single LPAR

- **1. Problem Description:** LPAR in service mode with a failed Device Adapter indicates a loss of access to data. Operational LPAR was not impacted.
- 2. Potential Impact of Problem: none
- 3. Problem Severity: Service4. Pervasive Problem: No

ID#: 298487

0x5171 MLE

- **1.Problem Description:** Track that was destaged is partially restaged from NVS. Subsequent re-access of track without full restage caused a Microcde Logic Error
- 2. Potential Impact of Problem: Warmstart
- **3.Problem Severity:** Service **4.Pervasive Problem:** No

ID#: 298533

HMC Healthcheck failed at: verifyHMCFileSystemSize

- 1. **Problem Description:** Accumulation of monitor files from processes that have exited.
- 2. Potential Impact of Problem: none
- Problem Severity: Service
 Pervasive Problem: No

ID#: 299747

0x0103 MLE

- **1. Problem Description:** CS tries to map an invalid segment because it's accessing a sidefile entry before the entry is complete. This causes a Microcode Logic Error.
- 2. Potential Impact of Problem: Warmstart
- Problem Severity: Service
 Pervasive Problem: No

Code update suspended

1. Problem Description: During p7 firmware update SRC B1818A10 is logged, causing CDA to suspend

2. Potential Impact of Problem: Extended service action

Problem Severity: Service
 Pervasive Problem: No

ID#: 299924

0x05E0 MLE

1. **Problem Description:** Global Mirror collision and Global Copy collision on the same track triggers a Microcode Logic Error if the volume is removed from the session while Global Copy transfer is still pending.

2. Potential Impact of Problem: Warmstart

Problem Severity: Service
 Pervasive Problem: No

ID#: 300069

Excessive MRPD data transmit time

1. Problem Description: Collection of data for logicalVolume and logicalSubsystem caused MRPD dataset to become very large.

2. Potential Impact of Problem: none

3. Problem Severity: Service4. Pervasive Problem: No

ID#: 300113

Assist OnSite (AOS) disabled after HMC update

1. **Problem Description:** Default setting after reinstalling AOS filesets is to disable AOS.

2. Potential Impact of Problem: Must re-enable AOS after update

3. Problem Severity: Service4. Pervasive Problem: Yes

ID#: 300834

FlashCopy Manager script failure

1. **Problem Description:** Failure was caused by malformed UnitSerial field in inquiry page C2h

2. Potential Impact of Problem: Scripting fails

3. Problem Severity: Service4. Pervasive Problem: No

Improvements: Improvement for better usability

Remove Apache Struts v1 from GUI

1. **Problem Description:** On April 30, 2014, a critical Apache Struts vulnerability was published at http://web.nvd.nist.gov/view/vuln/detail?vulnId=CVE-2014-0114, with a score high enough to require a fix as soon as possible. It is noted that Apache Struts 1.x is now EOL and cannot be simply replaced with a newer version without significant code rework.

It has been decided to simply eliminate all GUI usage of Apache Struts, and use new Java servlets instead.

Potential Impact of Problem: none
 Problem Severity: Improvement

4. Pervasive Problem: No

ID#: 296806

Easy Tier data collection improvements

1. Problem Description: Add sub-tasks to the Easy Tier data collection by area task, and reduce the size of individual sub-packages

Potential Impact of Problem: none
 Problem Severity: Improvement

4. Pervasive Problem: No

ID#: 297112

Easy Tier data collection improvements

1. Problem Description: Provide additional functions to collect Easy Tier logs and Easy Tier traces by date

Potential Impact of Problem: none
 Problem Severity: Improvement

4. Pervasive Problem: No

ID#: 299028

Allow secondary HMC to report powerfail/firehose dump

1. Problem Description: If power is lost to the base rack, the integrated HMC is unable to report the event. If a secondary HMC exists, this improvement will allow it to report the event.

Potential Impact of Problem: none
 Problem Severity: Improvement

4. Pervasive Problem: No

ID#: 299134

WebSM/AOS callhome change

1. Problem Description: Update callhome records with AOS information

Potential Impact of Problem: none
 Problem Severity: Improvement

4. Pervasive Problem: No

Enable Global Copy Collision sidefile by default1. Problem Description: Changes the default setting to enabled.

2. Potential Impact of Problem: none 3. Problem Severity: Improvement

4. Pervasive Problem: No

Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries > S/390
- > 0/3/0
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at http://www.ibm.com/legal/us/en/copytrade.shtml. Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

Notices

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing

IBM Corporation
North Castle Drive
Armonk, NY 10504-1785
U.S.A.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law:

INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.