



Service discontinuance: Firmware support for selected IBM DataPower 9235 models

Table of contents

- [1 Overview](#)
- [1 Withdrawn products](#)
- [2 Replacement product information](#)

Overview

Effective March 31, 2014, IBM® will withdraw the standard support Microcode Remote Support Agreement (MCRSA) contract for selected IBM DataPower® 9235 appliance models. Existing MCRSA firmware support contracts can be renewed through March 31, 2014.

For renewals or questions regarding extended support coverage, contact your IBM Technical Support sales representative.

The existing Hardware maintenance service contracts are renewable through March 31, 2016.

Withdrawn products

WebSphere® DataPower appliance support

Program name	PID number	Effective withdrawal date
WebSphere DataPower Support Registration	5771-DTP	March 31, 2014

Firmware support for the following WebSphere DataPower appliances is withdrawn.

DataPower machine models, previously withdrawn from marketing :

Description	Machine	Model
IBM WebSphere DataPower XML Accelerator XA35	9235	22X
IBM WebSphere DataPower XML Security Gateway XS40	9235	32X
IBM WebSphere DataPower XML Security Gateway XS40 with HDD	9235	3BX
IBM WebSphere DataPower XML Security Gateway XS40 with HSM	9235	34X
IBM WebSphere DataPower XML Security Gateway XS40 with HSM and HDD	9235	3DX
IBM WebSphere DataPower Integration Appliance XI50	9235	42X
IBM WebSphere DataPower Integration Appliance XI50	9235	4BX

with HDD		
IBM WebSphere DataPower Integration Appliance XI50 with XG4	9235	43X
IBM WebSphere DataPower Integration Appliance XI50 with XG4 and HDD	9235	4CX
IBM WebSphere DataPower Integration Appliance XI50 with HSM	9235	44X
IBM WebSphere DataPower Integration Appliance XI50 with HSM and HDD	9235	4DX
IBM WebSphere DataPower Integration Appliance XI50 with HSM and XG4	9235	45X
IBM WebSphere DataPower Integration Appliance XI50 with HSM, XG4, and HDD	9235	4FX
IBM WebSphere DataPower B2B Appliance XB60	9235	62X
IBM WebSphere DataPower Low Latency Appliance XM70	9235	6BX
IBM WebSphere DataPower Low Latency Appliance XM70 with Fibre Channel	9235	6FX

Replacement product information

None

Trademarks

IBM, DataPower and WebSphere are registered trademarks of IBM Corporation in the United States, other countries, or both.

Other company, product, and service names may be trademarks or service marks of others.

Terms of use

IBM products and services which are announced and available in your country can be ordered under the applicable standard agreements, terms, conditions, and prices in effect at the time. IBM reserves the right to modify or withdraw this announcement at any time without notice. This announcement is provided for your information only. Additional terms of use are located at

<http://www.ibm.com/legal/us/en/>

For the most current information regarding IBM products, consult your IBM representative or reseller, or visit the IBM worldwide contacts page

<http://www.ibm.com/planetwide/us/>